













101 Model. WZJ322







102 Model. WZJ321



103 Model. WZJ120-A







104 Model. WZJ860-A







Model	Class	Description	Measuring Range
WZJ322,WZJ321	1.5	DCA Meter	100-1000 μ A
WZJ120-A	1.5	DCA Meter	50-500 μ A 1-500mA 1-30A
WZJ860-A		DCV Meter	1-600V
		ACA Meter	0.1-30A
		ACV Meter	3-600V





05 Model. WZJ120-B







06 Model. WZJ860-B



107 Model. WMU52







108 Model. WMU45







Model	Class	Description	Measuring Range
WZJ120-B	1.5	DCA Meter	50-500 μ A 1-500mA 1-30A
WZJ860-B		DCV Meter	1-600V
		ACA Meter	0.1-30A
		ACV Meter	3-600V
WMU52	2.5	DCA Meter	50-500 μ A 1-500mA
WMU45		DCV Meter	1-600V
		ACV Meter	3-600V





109 Model. WZJ670







110 Model. WZJ460



111 Model. WZJ850







112 Model. WZJ540







Model	Class	Description	Measuring Range
WZJ670	2.5	DCA Meter	50-500 μ A 1-500mA 1-30A
WZJ460	2.5	DCV Meter	1-600V
WZJ850	2.5	ACA Meter	0.1-30A
WZJ540	2.5	ACV Meter	3-600V





13 Model. WZJ670-A







14 Model. WZJ670-C



15 Model. WZJ460-A







16 Model. WZJ811T







Model	Class	Description	Measuring Range
WZJ670-A	2.5	DCA Meter	100-500 μ A 1-500mA IA
WZJ670-C	2.5	DCV Meter	1-600V
WZJ460-A	2.5	ACA Meter	5-250A
WZJ811T	2.0	DCA Meter	500mA
		DCV Meter	8V-200V





Model. W59C23







Model. W44C17



Model. W69C17







Model. W85C17







Model	Class	Description	Measuring Range
W59C23	1.5	DCA Meter	50-500 μ A 1-500mA 1-10A (Attach FI-2 Shunt over 15A in addition)
W44C17	1.5	DCV Meter	1-600V
W69C17	2.5	ACA Meter	0.5A-20A (Provide Current Mutual Inductor over 20A)
W85C17	2.5	ACV Meter	3-600V





121 Model. W59C2







122 Model. W44C2



123 Model. W69C9







124 Model. W85C1







Model	Class	Description	Measuring Range
W59C2	1.5	DCA Meter	50-500 μ A 1-500mA 1-10A (Attach FI-2 Shunt over 15A in addition)
W44C2	1.5	DCV Meter	1-600V
W69C9	2.5	ACA Meter	0.5A-20A (Provide Current Mutual Inductor over 20A)
W85C1	2.5	ACV Meter	3-600V




125 Model. W69C13







126 Model. W85C5



127 Model. TN-38







28 Model. TRR50NC







Model	Class	Description	Measuring Range
W69C13	2.5	DCA Meter	50-500 μ A 1-500mA 1-10A (Attach FI-2 Shunt over 15A in addition)
W85C5		DCV Meter	1-600V
		ACA Meter	0.5A-20A (Provide Current Mutual Inductor over 20A)
		ACV Meter	3-600V
TN-38	2.5	DCA Meter	50-500 μ A 1-500mA 1-10A (Attach FI-2 Shunt over 15A in addition)
TRR50NC		DCV Meter	1-600V
		ACA Meter	0.5A-20A (Provide Current Mutual Inductor over 20A)
		ACV Meter	3-600V





29 Model. WZJ48W







130 Model. W69C1



131 Model. W88C2



132 Model. W99C2/1



Model	Class	Description	Measuring Range
WZJ48W	5	DCA Meter DCV Meter ACV Meter	100-500 μ A 1-500mA 1A (Attach FI-2 Shunt over 2A in addition) 1-600V 5-250V
W69C1	2.5	DCA Meter	50-500 μ A 1-30mA
W88C2	2.5	DCA Meter	50-500 μ A 1-30mA
W99C2/1	2.5	DCA Meter	50-500 μ A 1-30mA